

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:					
Company	Dennis Ware Controller				
OGM	Steve Demczak Environmental Scientist III				

Inspection Report

Permit Number:			
Inspection Type:			
Inspection Date:	Tuesday, October 16, 2007		
Start Date/Time:	10/16/2007 10:00:00 AM		
End Date/Time:	10/16/2007 12:00:00 PM		
Last Inspection:	Wednesday, September 26, 2007		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 50's

InspectionID Report Number: 1439

Accepted by: dhaddock

10/31/2007

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP

Site: WILLOW CREEK MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operations		
14,662.49	Total Permitted	✓ Federal	✓ Underground		
71.44	Total Disturbed	☐ State	☐ Surface		
	Phase I	☐ County	✓ Loadout		
	Phase II	✓ Fee	☐ Processing		
	Phase III	✓ Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee notified the Division on May 7, 2007 that the second quarter of 2007 surface and UPDES water monitoring information for the Willow Creek Mine was in the electronic data base pipeline ready for uploading. The only site having no flow was B-25 in Crandall Canyon.

The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit, which was renewed April 24, 2006.

There are no pending compliance actions.

There is currently no activity at this site.

Inspector's Signatu	re
---------------------	----

Steve Demczak, Environmental Scientist III

Date

Thursday, October 18, 2007

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Tuesday, October 16, 2007

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil	✓		V	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	V		V	
11.	Contemporaneous Reclamation		V		
12.	Backfilling And Grading	V		V	
13.	Revegetation	✓		✓	
14.	Subsidence Control		V		
15.	Cessation of Operations		✓		
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038
Inspection Type: PARTIAL

Inspection Date: Tuesday, October 16, 2007

Page 3 of 3

3. Topsoil

All topsoil has been used at the site.

4.a Hydrologic Balance: Diversions

Diversion were open and would function as designed in a storm event.

4.d Hydrologic Balance: Water Monitoring

Water monitoring was taken for the second quarter and was submitted to the Division.

8. Noncoal Waste

The site was clear of non-coal waste materials.

10. Slides and Other Damage

No slides were noticed during the inspection.

12. Backfilling And Grading

The site is backfilled and graded.

13. Revegetation

The site is revegetated. Some areas have more vegetation that others.